

Letra	Números de registro De - A		Clase de máquina (nº de modelo)	Cantidad asignada	Fecha de adjudicación	Año de adjudicaci ón	Notas
S-	1	9	3k	9	JAN.-JUNE	1906	
S-	10	29	5k/6k/8k/9k	20	JAN.-JUNE	1906	
S-	30	39	14k	10	JAN.-JUNE	1906	
S-	40	150039	15K	150000	JAN.-JUNE	1906	
S-	150040	150239	15K C.S.	200	JAN.-JUNE	1906	
S-	150240	150264	15K C.S.	25	JAN.-JUNE	1906	
S-	150265	190264	16K	40000	JAN.-JUNE	1906	
S-	190265	190314	16K C.S.	50	JAN.-JUNE	1906	
S-	190315	190324	22K	10	JAN.-JUNE	1906	
S-	190325	190334	22K	10	JAN.-JUNE	1906	
S-	190335	190344	23 Cloth	10	JAN.-JUNE	1906	
S-	190345	190354	23 Leather	10	JAN.-JUNE	1906	
S-	190355	250354	27K	60000	JAN.-JUNE	1906	
S-	250355	475354	28K	225000	JAN.-JUNE	1906	
S-	475355	485354	29K	10000	JAN.-JUNE	1906	
S-	485355	487854	29K31	2500	JAN.-JUNE	1906	
S-	487855	497854	31K	10000	JAN.-JUNE	1906	
S-	497855	497954	31K	100	JAN.-JUNE	1906	
S-	497955	500954	34K	3000	JAN.-JUNE	1906	
S-	500955	505954	44K	5000	JAN.-JUNE	1906	
S-	505955	507954	45K	2000	JAN.-JUNE	1906	
S-	507955	507964	45K60/1	10	JAN.-JUNE	1906	
S-	507965	508064	46K1 & 2	100	JAN.-JUNE	1906	

S-	508065	508164	46K13 & 14	100	JAN.-JUNE	1906	
S-	508165	509164	46K25 & 27	1000	JAN.-JUNE	1906	
S-	509165	509194	47K	30	JAN.-JUNE	1906	
S-	509195	549194	48K	40000	JAN.-JUNE	1906	
S-	549195	549694	49K	500	JAN.-JUNE	1906	
S-	549695	549699	3K	5	JAN.-JUNE	1906	
S-	549700	549709	5k/6k/8k/9k	10	JAN.-JUNE	1906	
S-	549710	549724	14K	15	JAN.-JUNE	1906	
S-	549725	549734	14K	10	JAN.-JUNE	1906	
S-	549735	552234	15K	2500	JAN.-JUNE	1906	
S-	552235	555734	16K	3500	JAN.-JUNE	1906	
S-	555735	555749	22K	15	JAN.-JUNE	1906	
S-	555750	555764	23 Cloth	15	JAN.-JUNE	1906	
S-	555765	555769	23 Leather	5	JAN.-JUNE	1906	
S-	555770	557769	27K	2000	JAN.-JUNE	1906	
S-	557770	559769	28K	2000	JAN.-JUNE	1906	
S-	559770	560019	29K	250	JAN.-JUNE	1906	
S-	560020	560069	29K31	50	JAN.-JUNE	1906	
S-	560070	560369	31K	300	JAN.-JUNE	1906	
S-	560370	561369	33K	1000	JAN.-JUNE	1906	
S-	561370	561469	33K	100	JAN.-JUNE	1906	
S-	561470	561519	34K	50	JAN.-JUNE	1906	
S-	561520	561619	44K	100	JAN.-JUNE	1906	
S-	561620	561719	45K	100	JAN.-JUNE	1906	
S-	561720	561744	46K1 & 2	25	JAN.-JUNE	1906	
S-	561745	561769	46K13 & 14	25	JAN.-JUNE	1906	
S-	561770	561819	46K25 & 27	50	JAN.-JUNE	1906	

S-	561820	561919	48K	100	JAN.-JUNE	1906	
S-	561920	561969	49K1 & 2	50	JAN.-JUNE	1906	
S-	561970	561989	47K	20	JAN.-JUNE	1906	
S-	561990	562009	47K	20	JAN.-JUNE	1906	
S-	562010	562034	16K C.S.	25	JAN.-JUNE	1906	
S-	562035	562039	5k/6k/8k/9k	5	JULY-DEC.	1906	
S-	562040	562044	14K	5	JULY-DEC.	1906	
S-	562045	762044	15K	200000	JULY-DEC.	1906	
S-	762045	762144	15K C.S.	100	JULY-DEC.	1906	
S-	762145	812144	16K	50000	JULY-DEC.	1906	
S-	812145	812194	16K C.S.	50	JULY-DEC.	1906	
S-	812195	812204	22K	10	JULY-DEC.	1906	
S-	812205	812209	23 Cloth	5	JULY-DEC.	1906	
S-	812210	887209	27K	75000	JULY-DEC.	1906	
S-	887210	1162209	28K	275000	JULY-DEC.	1906	
S-	1162210	1172209	29K	10000	JULY-DEC.	1906	
S-	1172210	1175709	29K31	3500	JULY-DEC.	1906	
S-	1175710	1195709	31K	20000	JULY-DEC.	1906	
S-	1195710	1197209	33K	1500	JULY-DEC.	1906	
S-	1197210	1201209	34K	4000	JULY-DEC.	1906	
S-	1201210	1206209	44K	5000	JULY-DEC.	1906	
S-	1206210	1208709	45K	2500	JULY-DEC.	1906	
S-	1208710	1208809	46K1 & 2	100	JULY-DEC.	1906	
S-	1208810	1209809	46K25 & 28	1000	JULY-DEC.	1906	
S-	1209810	1209819	47K	10	JULY-DEC.	1906	
S-	1209820	1254819	48K	45000	JULY-DEC.	1906	
S-	1254820	1255519	49K1 & 2	700	JULY-DEC.	1906	

S-	1255520	1255529	22K	10	JULY-DEC.	1906	
S-	1255530	1255549	22K	20	JULY-DEC.	1906	
S-	1255550	1257049	29K31	1500	JULY-DEC.	1906	
S-	1257050	1257059	5k/6k/8k/9k	10	JAN.-JUNE	1907	
S-	1257060	1257069	14K	10	JAN.-JUNE	1907	
S-	1257070	1477069	15K	220000	JAN.-JUNE	1907	
S-	1477070	1532069	16K	55000	JAN.-JUNE	1907	
S-	1532070	1532079	22K	10	JAN.-JUNE	1907	
S-	1532080	1532089	22K	10	JAN.-JUNE	1907	
S-	1532090	1592089	27K	60000	JAN.-JUNE	1907	
S-	1592090	1812089	28K	220000	JAN.-JUNE	1907	
S-	1812090	1824089	29K	12000	JAN.-JUNE	1907	
S-	1824090	1827589	29K31	3500	JAN.-JUNE	1907	
S-	1827590	1837589	31K	10000	JAN.-JUNE	1907	
S-	1837590	1842589	34K	5000	JAN.-JUNE	1907	
S-	1842590	1846089	45K	3500	JAN.-JUNE	1907	
S-	1846090	1846099	45K60	10	JAN.-JUNE	1907	
S-	1846100	1846299	46K1 & 2	200	JAN.-JUNE	1907	
S-	1846300	1846399	46K13 & 14	100	JAN.-JUNE	1907	
S-	1846400	1846899	46K25 & 28	500	JAN.-JUNE	1907	
S-	1846900	1846949	47K	50	JAN.-JUNE	1907	
S-	1846950	1861949	48K	15000	JAN.-JUNE	1907	
S-	1861950	1862649	49K1 & 2	700	JAN.-JUNE	1907	
S-	1862650	1877649	66K	15000	JAN.-JUNE	1907	
S-	1877650	1878149	29K31	500	JAN.-JUNE	1907	
S-	1878150	1878159	14K	10	JULY-DEC.	1907	
S-	1878160	2078159	15K	200000	JULY-DEC.	1907	

S-	2078160	2078209	15K C.S.	50	JULY-DEC.	1907	
S-	2078210	2123209	16K	45000	JULY-DEC.	1907	
S-	2123210	2123259	16K C.S.	50	JULY-DEC.	1907	
S-	2123260	2123269	22K	10	JULY-DEC.	1907	
S-	2123270	2123279	23 Cloth	10	JULY-DEC.	1907	
S-	2123280	2188279	27K	65000	JULY-DEC.	1907	
S-	2188280	2388279	28K	200000	JULY-DEC.	1907	
S-	2388280	2405279	29K	17000	JULY-DEC.	1907	
S-	2405280	2417279	31K	12000	JULY-DEC.	1907	
S-	2417280	2418279	45K	1000	JULY-DEC.	1907	
S-	2418280	2419279	46K25 & 28	1000	JULY-DEC.	1907	
S-	2419280	2419529	49K	250	JULY-DEC.	1907	
S-	2419530	2424529	66K	5000	JULY-DEC.	1907	
S-	2424530	2424729	66K	200	JULY-DEC.	1907	
S-	2424730	2424929	46K1 & 2	200	JULY-DEC.	1907	
S-	2424930	2425029	46K13 & 14	100	JULY-DEC.	1907	
S-	2425030	2425059	15K C.S.	30	JULY-DEC.	1907	